FIELD INSPECTION REPORT

Date of Inspection: 3.12.20			District: Kaimes	
Division: Blabbug			Length (km): 2 :544	
Name of	the Road:	Satianoan to Kan	2 RY	
Scheme/Programme: N		MAINTENANCE		
Package	No.: NR-1/19	019-20/10	Road Id No.: 10109634	
Status of the Project:		Orgoing/Completed	Under Maintenance Profile et	some his
Work is	a case of:	New Connectivity/U	p gradation/ Maintenance	
Sl. No.		Parameters to	be checked	Remarks
1.	Pavement	-1	to the second	
a)	Road Junction condition			S/U M/A
b)	Condition of Surfacing			S/U /4
c)	Riding Quality			S/U 🗸
d)	Road Camber			S/U 🚜
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No 💉
f)	Contraction Joints provided or not (CC Pavement)			Yes/No 🎠
g)	Compaction of flank/slope & raincuts if any			Yes/No 🛵
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U M

Condition of Abutment & Wing walls, Slab in RCC culverts

stones/Pavement road markings are provided and maintained

Whether sign boards/informatory/cautionary Board/km & 200m

Condition of railings/slab/approach for Bridges

Overall Rating

b)

c)

3.

a)

4.

2)

Satisfactory (S)	ν
Satisfactory but requires Improvement (SRI)	SRI.
Unsatisfactory (U)	

(Signature)

S/SRI/U x

Yes/No

S/SRI/U K//

NAME: Sirendra Kumar

Road Furniture

Compliance History

Status of ATR's & any others

DESIGNATION: 7.4

Scanned with CamScanner