FIELD INSPECTION REPORT

| | LIELD INS | PECTION REPORT | |
|--------------------------------|--|---|-----------|
| | Inspection: 2.12.20 | | |
| Division | on:- Whafana Length (Km):- 2 2514 | | |
| Name o | Road:- Hans pranhand A | Length (Km): 2.050 4 rd ntang at 141-31 (hukti over n thatha tak path ha Jinno Maintenance | Bridge se |
| Scheme | Programme: 2 class was a few | Maine Lan path Ha Jinno | dhar. |
| Package No.:- | | Road ID No. :- | |
| Status of Project:- on going | | | |
| Work is a case of: Elw started | | Ongoing/Complete/Under Maintenance | |
| Sl. No. | ・ 10 円 ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ | New Connectivity/Up gradation/ Mainte | |
| 1. | Pavement | ters to be cheeked Remarks | |
| | Control of the second s | | |
| a) | Road Junction Condition | | S/U |
| b) | Condition of Surface | | S/U |
| c) | Riding Quality | | S/U |
| d) | Road Camber | | S/U |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | | Yes/No |
| f) | Contruction Joints provided or not (CC Pavement) Yes/No | | Yes/No |
| g) | Compaction of flank/slope & raincuts if any | | Yes/No |
| 2. | Cross Drainage | | |
| a) · | Condition of head walls in Hume pipe culverts including its painting | | S/SRI/U |
| b) | Condition of Abutment & Wing walls, Slab in RCC Culverts | | S/SRI/U |
| c) | Condition of railings/slab/approach for Bridges | | S/SRI/U |
| 3. | Road Furniture | | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200 m stone/ Pavement road markings are provided and maintained Yes/No | | |
| 4. | Compliance History | | |
| a) | Status of ATR's & any others | | |
| , | | | |

Overall Rating:

| Satisfactory (S) | S |
|--------------------------------------|---------|
| Satisfactory but requires Inprovemen | t (SRI) |
| Unsatisfactory (U) | |

(Signature)