FIELD INSPECTION REPORT

Date of Ir	nspection: 44	0.12.2020	District: Bhathua (Co	iwer)
Division: Bhabhus,			Length (km): 1.300	
Name of	the Road: Ho		urate Pathto Mas	01
	Programme:	MAINTENANCE		
Package Status	No.: MR-N/2			41032416
Status of the Project: Work is a case of:		Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance		
Sl. No.	SPACE CALL		and the second s	
	Dansan	rarameters to	ре спескед	Kelliarka
	Pavement	يأرىء .	addition of the distance	
a)	Road Junction condition			S/U
b)	Condition of Surfacing			V S/U
c)	Riding Quality			✓S/U
d)	Road Camber			VS/U
c)	Whether free aggregates in	Yes/No M		
f)	Contraction Joints provided or not (CC Pavement)			Yes/No /
g)	Compaction of flank/slope & raincuts if any			Yes/No V
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign stones/Pavem	Yes/No		
4.	Compliance History			
a)	Status of ATI	R's & any others		

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	_
Unsatisfactory (U)	

03.12.2020

(Signature)

NAME: Bineudra Cumar Single DESIGNATION: A.E. Charing up