FIELD INSPECTION REPORT

ate of a	spection: n2 12 2 n20 District: (Beautonal	
	rection: 03.12.2020 District: 12 TELDHICA Length (km	Begusarau	
	he Road: PWD Road to Forte	ha Station.	
	rogramme: MAINTENANCE		
	No .: PM BE TEN 19 0009 Road Id No	o.: 320107103305	59
	the Project: Ongoing/Completed/Under Maint	itenance	
Work is a	a case of: New Connectivity/Up gradation/	Maintenance	
Sl. No.	Parameters to be checked	Re	marks
1.	Pavement		
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U Aug way
e)	Whether free from defects such as visible aggregates in case of CC Pavement.	le cracks, exposed	Yes/No Yes/No Yes/No Hull
f)	Contraction Joints provided or not (CC Pavemen	nt)	Yes/No done
g)	Compaction of flank/slope & raincuts if any		Yes/No hly de
2.	Cross Drainage		/ 6m2
a)	Condition of head walls in Hume pipe culverts	including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts S/SRI/U		
c)	Condition of railings/slab/approach for Bridges S/SRI/U		
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.	Compliance History		
a)	Status of ATR's & any others		
Overal	Rating : Satisfactory (S)		
	Satisfactory but requires la	mprovement (SRI)	
	Unsatisfactory (U)		
		0	-
		gn	1203/12/2000 HIN
		0	63/17/2020 ALV
		(Signa	iture) /

NAME: UHESH KUMBR HAHTO
DESIGNATION: JUNIOR EMUNIMEER