FIELD INSPECTION REPORT

ate of Ins	spection: 0 v	1/12/2020	Matrici: Nalanda	
lvision: Biharsham			Length (km): 0/605fr	
	the same of the sa	131 To Paithna	Laucas a Dubri	611 - 0-10
	rogramme:	MAINTENANCE	New manuferance politi	9-2018
ackage N		A I Manual II	Road Id No.: /Under Maintenance Ju fender	mocest
	the Project:	Van Canastinity/	Up gradation/ Maintenance	
Vork is a Sl. No.	case of:	Parameters to		Remarks
	Pavement			
n)	Road Junction	condition	and published the second of th	S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2	Cross Drain	age		***
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U	
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			n Yes/No
774.	Compliance History			
a)	Status of A	TR's & any others		HEL

Overall Rating

Satisfactory (S))
Satisfactory but requires Improvement (SRI)	HA
Unsatisfactory (U)	

61/12/2020 (Signature)

NAME: Blood Kumar Stoph

DESIGNATION: JE

Scanned with CamScanner