FIELD INSPECTION REPORT

Date of Inspection:	03/12/20	District: Vaishali		
Division: Haribur		Length (km): 2.70		
Name of the Road:	Senduari beth	iya chaput Se Kutubbur Road	and the second	
Scheme/Programme:	MAINTENAN	VCE.	and the second section is	
Package No.:		Road Id No.:		
Status of the Project:	Ongoing Completed/Under Maintenance			
Work is a case of:	New Connecti	vity/Up gradation/ Maintenance	and the second	
Sl. No.	Parameto	ers to be checked Re	marks	

St. No.	CALLEGE CO. CO. Co.	
1.	Pavement	and the second second second second
a)	Road Junction condition	S/U U
b)	Condition of Surfacing	S/U U
c)	Riding Quality	S/U U
d)	Road Camber	S/U U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No .
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No.
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	_
Unsatisfactory (U)	U

SK 03:12:20 J.E

AE Hajpus

(Signature)

NAME:

DESIGNATION:

N/A