Execution of work is going on.

FIELD INSTECTION REPORT

Date of Inspection :	03.12.2020	District: Nalanda	
Division: Harr		Length (km): 1. 489 km	
Name of the Road:	N11309 to 1	gansigpu	
Scheme/Programme:	MAINTENANCE	01	
Package No.: MR-M	19-20/Halmout/0	Road Id No.:	
Status of the Project:	Qngoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing		
c)	Riding Quality		
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Remark! - Top surfacing of the road is remaining.

(Signature)

NAME: RAVI KUMAR

DESIGNATION: fr. Engineer