		FIELD INSPECTION REPORT	
Date of I	nspection : _	4/12/20 District: - David Langa	
Name of the Road: - Gualegachti Dasaul to Bairdubuz			
Name of	the Road: -G	ulategachti Dasaut to Bairawbur	path
Scheme/Programme: MAINTENANCE			
Package	No.: New Mai	uterance policy Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is	a case of:	New Connectivity/Up gradation/ Maintenance	
SL No.		Parameters to be checked	Remarks
ı.	Pavement		
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
(c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free aggregates in o	from defects such as visible cracks, exposed case of CC Pavement.	Yes/No
0		pints provided or not (CC Pavement)	Yes/No

Condition of head walls in Hume pipe culverts including its painting

Whether sign boards/informatory/cautionary Board/km & 200m

Condition of Abutment & Wing walls, Slab in RCC culverts

stones/Pavement road markings are provided and maintained

Informatory leowed

g)

2.

a)

b)

c)

3.

a)

a)

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Compaction of flank/slope & raincuts if any

Condition of railings/slab/approach for Bridges

Cross Drainage

Road Furniture

Compliance History

Status of ATR's & any others

(Signature)

NAME:

Yes/No

S/SRI/U

S/SRI/U

S/SRI/U

Yes/No