

FIELD INSPECTION REPORT

Date of Inspection :	3.12.2020	District:	Nalanda
Division :	Rajgir	Length (km):	3.600
Name of the Road:	Repair of road from Link road Babupur Ben Roy		
Scheme/Programme:	MAINTENANCE ✓		
Package No.:		Road Id No.:	10200908045
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	M+Stone Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	1 S.
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

[Signature]
3.12.2020
(Signature)

NAME: Shriprakash Kumar

DESIGNATION: A. E.

Scanned with CamScanner

Scanned with CamScanner