FIELD INSPECTION REPORT

		2 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2			
Date of Inspection: 03.12.1010			District: Bhabhu	a ([Cei mun]	
Division: Phalphua			Length (km): 3.6	Length (km): 3.60	
Name of	the Road: M	luxi to B	hadari Novad		
Scheme/	Programme:	MAINTENANCI	E		
Package No.: MR (3054			Road Id No.: _ 163	Road Id No.: 1630/400819	
Status of	the Project:	Ongoing/Comple	ted/Under Maintenance		
Work is a case of:		New Connectivity/Up gradation/ Maintenance			
Sl. No.		Parameters	to be checked	Remarks	
1.	Pavement				
a)	Road Junction			VS/U	

Whether free from defects such as visible cracks, exposed

Condition of head walls in Hume pipe culverts including its painting

Whether sign boards/informatory/cautionary Board/km & 200m

Condition of Abutment & Wing walls, Slab in RCC culverts

a)	Status o	tus of ATR's	
Overall	Rating	:	

c)

d)

c)

f)

g)

2. .

a)

b)

c)

3.

a)

stones/Pavemer	Yes/No.	
Compliance H		
Status of ATR'	s & any others	
Rating :		
	Satisfactory (S)	
	Satisfactory but requires Improvement (SRI)	SRI
	Unsatisfactory (U)	_

(Signature)

S/U

VS/U

VS/U

Yes/No 1

Yes/No

S/SRI/U

S/SRI/U

S/SRI/U

Yes/No.

YesNo NA

NAME: Birendra Kumar Single DESIGNATION: A.E. Charimpur

Condition of Surfacing

aggregates in case of CC Pavement.

Contraction Joints provided or not (CC Pavement)

Compaction of flank/slope & raincuts if any

Condition of railings/slab/approach for Bridges

Riding Quality

Road Camber

Cross Drainage

Road Furniture

Scanned with CamScanner