## FIELD INSPECTION REPORT

Date of I	nspection:	3-12-20	District: Gaya	
Division: Gaya Length (km): 3.301<11				
Name of	the Road:	Tekuna To	A _ 1 _ 1	
	Programme:	MAINTENANCE	3054 (old)	
Package	No.:		Road Id No.:	
			ed/Under Maintenance	
Work is	a case of:	New Connectivity/	Up gradation/ Maintenance	
SI. No.		Parameters to	be checked	Remarks
1,	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			SIU
c)	Riding Quality			S/U
d)	Road Camber			√S/Ū
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)			Yes/No NA
g)	Compaction of flank/slope & raincuts if any			Yes/No
2	Cross Drains	(g)		
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts  S/SRI/U			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U /
. 3.	Road Furnit			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4	Compliance	Burgay - Fig.		
8)	Status of AT	R's & any others	· · · · · · · · · · · · · · · · · · ·	NA
				The second secon

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Clandra Shibbur Komir

DESIGNATION: JU