**FIELD INSPECTION REPORT** 

Date of Inspection :		3/12/2020	District :	Bhagalp	our
Division :		Kahalgaon	Length (Km):	1.93	
Name o	of the Road:	Anadipur Pirp Path (Kahalga	oainti Road Harichak T aon)	o Babhan	gama Tak
Scheme	e / Programme	MAINTENANC	E		
Packag	e No. :		Road Id No.: 2070	340082	7
Status	of the Project :	<b>Under Mainte</b>			
Work is	a case of :	Maintenance			
SI. No.	Parameters to be Checked		Remarks		
1	Pavement	A STATE OF THE PROPERTY OF THE			
a)	Road Junction Condition			S/U	S
b)	Condition of Surfacing			S/U	S
c)	Riding Quality			S/U	S
d)	Road Camber			S/U	S
e) *	Whether free from defects such as visible cracks, exposed aggregatesv in case of CC Pavement			Yes/No	Yes
f)	Contraction Joints Provided or not (CC Pavement)			Yes/No	yes
g)	Compaction of flank/slope & raincuts if any			Yes/No	yes
2	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			Š/SRI/U	2
b) .	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	NA
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	NA
3	Road Furniture				
a)	Whether sign board/informatory/cautionary Board/Km & 200m stones/Pavement road markings are provided and maintained			Yes/No	Yes
4	Compliance Histor				
a)	Status of ATR's & ar	ny others			·No

Overall Rating:

Satisfactory (S)	S
Satisfactory but Improvement (SRI)	٨
Unsatisfactory (U)	8

(Signature)

Name: