## FIELD INSPECTION REPORT

Date of Inspection: 02.12.2020 Division: Haribur			District: Vaishali Length (km): 4.7	
and the second s	the Road:	The state of the s	भे पंचायत्र में नंद्रालयू	3110 428
to professional designation of the second second	Programme:	MAINTENANCE	article and the second	धित्रध्य
Package	The state of the s	The second secon	id Id No.1	and the second s
	the Project:	Ongoing/Completed/Und		and the second subsequent and the second of
White the state of the control of th	a case of:	New Connectivity/Up gra	adation/ Maintenance	and the second s
Sl. No.	100 AND STATE OF	Parameters to be cl	recked	Remarks
1.	Pavement	and the second s		
a)	Road Junction condition		S/U - 5	
	Condition of Surfacing			s/U - 5
b)	Riding Quality			S/U - 5
c)				S/U -4
d)	Road Camber		wisible gracks exposed	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No-5
0	Contraction Joints provided or not (CC Pavement)			Yes/No-5
0			Yes/No -	
g)	Compaction of flank/slope & raincuts if any			
2.	Cross Drainage			C'GDIA!
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
				Yes/No
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4.	Compliance History			M. Taranta
a)	Status of ATR's & any others			70

Overall Rating

Satisfactory (S)	>
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME:

D3.12.20

DESIGNATION: