FIELD INSPECTION REPORT

The second second	Inspection: 3.	12.2020 District: Faimur Length (km): 6.50	
Division	the Road: H	H30 Resorate via Salaun	dha
	Programme:	MAINTENANCE	
	No.: MPAY	19-20 Be Road Id No.	
	the Project:	Ongoing/Completed/Under Maintenance	
Vork is	a case of:	New Connectivity/Up gradation/ Maintenance	Remarks
Sl. No.		Parameters to be checked	Remarks
1.	Pavement		CILI
a)	Road Junction condition S/U		4
b)	Condition of S	ondition of Surfacing S/U	
c)	Riding Quality		S/U
d)	Road Camber		
e)	Whether free aggregates in	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
ſ)	Contraction Jo	pints provided or not (CC Pavement)	Yes/No
g)	Compaction o	Compaction of flank/slope & raincuts if any Yes/No	
2,	Cross Draina	ge at the second of the second	
a)	Condition of h	ead walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of A	Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of r	ailings/slab/approach for Bridges	S/SRI/U
3,	Road Furnitu	Road Furniture	
a)		Thether sign boards/informatory/cautionary Board/km & 200m yes/No ones/Pavement road markings are provided and maintained	
4.	Compliance l	listory	
a)	Status of ATR	's & any others	
Overall	Rating	Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)	
M	0te _	work not started	
			Not 2/12
NAME:	Mahand	en fel. gufa	nature) 3/1