FIELD INSPECTION REPORT

ate of Inspection: 03.12.2020 District: Bhabhua (Caimer)					
	Bhashu		Length (km): 0.850		
Same of the	he Road: Lo	17 Bhadaure	to chainpur 152a	Roud	
Scheme/P	rogramme:	MAINTENANCE			
Package No.: MR-N/2019-2013 Road Id No.: 1030/402016 Status of the Project: Ongoing/Completed/Under Maintenance					
Status of t					
Work is a	case of:		ivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked			Remarks	
1.	Pavement	-		A STATE OF	
a)	Road Junction condition			√S/U	
b)	Condition of Surfacing			√S/U	
c)	Riding Quality			√S/U	
d)	Road Camber			S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				
f)	Contraction Joints provided or not (CC Pavement)			Yes/No 14	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts S/SRI/U			S/SRI/U N	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U N	
3.	Rond Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
4.	Compliance	History			
a)	Status of ATI	R's & any others			

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	

03.12.2020 (Signature)

NAME: Birendra Kumer Singh DESIGNATION: A.E. Charing ur

Scanned with CamScanner