FIELD INSPECTION REPORT

Date of Inspection: 2-12-2020		District: Samasti Pul		
Division: R.w.D. Doulsing & sazar		Length (km): 8.2001au		
Name of the Road: Lagona, mushapur Bathur pur Anuruli				
Scheme/Programme:	MAINTENANCE	MR Old.		
Package No.:		Road Id No.:		
Status of the Project:	Ongoing/Completed/Under Maintenance			
Work is a case of:	New Connectivity/Up gradation/ Maintenance			

l. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	1
Unsatisfactory (U)	

(Signature)

NAME:
DESIGNATION: JE