


FIELD INSPECTION REPORT

Date of Inspection : 2/12/20		District: Murabbarpur
Division : Murabbarpur East-2		Length (km): 0.750 km
Name of the Road: Repair of Road from NH-57 to Old PWD Path Beruwa		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance ☒	
Work is a case of:	New Connectivity/Up gradation/ Maintenance ☒	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S ☒ U
b)	Condition of Surfacing	S ☒ U
c)	Riding Quality	S ☒ U
d)	Road Camber	S ☒ U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	No ☒ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes ☒ Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes ☒ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S ☒ SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N/A S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes ☒ No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	S ☒ U
Unsatisfactory (U)	


 2/12/20
 50