FIFE D INSPECTION REPORT

		FIELD HAST BETTEL		1 - 1 b
Date o	of Inspection:	4/12/20		Barbhanga
Division:		Warbhanga	Length(Km):	1.95
Name of Road:		NH57 to Kadisabad		
Scheme/Progrmme:		Maintenance (3054)		
			Road Id No.	V ₁
Package No.		Ongoing/Gompleted/ Under Maintenance		2
Status of the Project:		New Connectivity/Up gradation/Maintenance		
Wo	rk is a case of :			Remarks
S No.	Parameters to be Checcked Remarks			Kemarks
1	Pavement			C/II 7
a)	Road Junction condition			S/U S/U
b)	Condition of Surfacing			
c)	Riding Quality			S/U
d)	Road Camber			S/U
	Whether free from defects such as visible cracks, exposed			3/0
e)	aggregates in case of CC Pavement			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank /slope & raincuts if any			Yes/No
2	Cross Drainage			
	Condition of head walls in Hume pipe culverts including its			7
a)	painting			S/SRI/U
b)	Condition of Abutment & Wing walls , Slabs in RCC culverts			s/sri/u
c)	Condition of railing /slabs/ approach for Bridges			S/SRI/U
3	Road Furniture			
	Whethersign boards/informatory/-cautionary-Board / Km-&			
a)	200m stones / Pavement road markings are provided and			Yes/No Yes
	maintained Road matcking			. , , ,
3	Complianace History			
a)	Status of ATR's & any others			N·A
Overa	ll Rating:			
	J	Satisfactory (S)		
		Satisfactory but requires l	mprovement (SBI)	
		Unsatisfactory (U)	mprovement (SKI)	
	Colombia Da Va		1 1-01-	00 00:00
. 10	400 m asayn	Constructed an	a work in	rogress

Name:

Designation:

(Signature)