## FIELD INSPECTION REPORT

		FIELD INSPEC	CTION REPORT	
Date of Inspe	e of Inspection: 03/12/020 District: Buxas.			
Division (wDBuras			Length (km): 3.300 KM	
Name of the l		appear to Niya	iépus	
Scheme/Prog	ramme:	MAINTENANCE	14R 3054 new Maintenance	Policy -2018.
Package No.: 14R-N/19-20 Bux91/09 Road Id No.:			-	
Status of the			/Under Maintenance complete	9
Work is a cas			Jp gradation/ Maintenance	Remarks
Sl. No.		Parameters to	Parties and the second	Carried Total Control
1. Pay	ement	de ministra		
a) Roa	Road Junction condition			√8/U
b) Cor	Condition of Surfacing			₽S/U
c) Rid	Riding Quality			√S/U
d) Roa	Road Camber —			SAU_
	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No NA
	Contraction Joints provided or not (CC Pavement)			Yes/No-NA
	Compaction of flank/slope & raincuts if any			Yes/No NA
a particular commercial and the second of	Gross Drainage.			
a) Con	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U NA
A Secretary	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U NA
A STATE OF THE PROPERTY OF	Condition of railings/slab/approach for Bridges			S/SRI/U MA
THE RESERVE AND ADDRESS OF THE PARTY OF THE	Road Rurniture			
WILL	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			~Yes/No
	Compliance Bullion			
THE RESERVE OF THE PARTY OF THE	Status of ATR's & any others			NO
State of the state		A STATE OF THE STA	v.	
Overall Ratin	Overall Rating Satisfactory (S)			
	Satisfactory but requires Improvement (SRI)			
		Unsatisfactory (		
			(S	(1200) 02)12/020 15.6 Si

DESCENATIONS (SAN KA

Costrol 20 03/10/20