

FIELD INSPECTION REPORT

Date of Inspection:	02.12.2020	District:	DARBHANGA
Division:	DARBHANGA-2	Length(Km):	8.0 K.M.
Name of Road:	NH-105 DOME TO SHISO TAK		
Scheme/Programme:	Maintenance (MIR) 3054		
Package No.		Road Id No.	
Status of the Project:	Ongoing/Completed/ Under Maintenance ✓		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓		
S No.	Parameters to be Checked	Remarks	
1	Pavement		
a)	Road Junction condition	S S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank /slope & raincuts if any - Rain cuts due to flood	Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slabs in RCC culverts	S/SRI/U	
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/U	
3	Road Furniture		
a)	Whethersign boards/ infromatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	✓ Yes/No	
3	Complianace History		
a)	Status of ATR's & any others	NO	

Overall Rating: **SRS**

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRS
Unsatisfactory (U)	

[Signature]
02.12.2020
AE
(Signature)

Name: **HARERAM**
Designation: **J.E**

[Signature]
2.12.2020
J.E