FIELD INSPECTION REPORT

| Date of | Inspection: | 3/12/2020 | /12/2020 District: | | ACAWAM | |
|--|--|--|--|--|--|--|
| Division: | | NAWADA | Length (km): | 0.600 km | | |
| Name of | f the Road: - | Kuərma | - Sakebchak | | | |
| | Programme: | MAINTENANCE | | | | |
| | | -20/Nawada/12 | Road Id No.: | The state of the s | | |
| Maria Canada de Cara d | f the Project: | Ongoing/Complet | ed/Under Maintenance | The second second second second | Algeria de la constantina del constantina de la constantina del constantina de la co | |
| Work is | a case of: | New Connectivity | /Up gradation/ Maintenance | | | |
| Sl. No. | | Parameters | to be checked | - | Remarks | |
| 1. | Pavement | | | | | |
| a) | Road Junction condition | | | | S/U | |
| b) | Condition of Surfacing | | | S/U | | |
| c) | Riding Quality - | | | _S/U | | |
| d) | Road Camber | | | S/U | | |
| e) | 1111 La almanad | | | | Yes/No | |
| f) | Contraction Joints provided or not (CC Pavement) | | | | Yes/No | |
| g) | Compaction of tlank/slope & raincuts if any | | | | Yes/No | |
| 2. | Cross Drainag | · · · · · · · · · · · · · · · · · · · | | | | |
| a) | Condition of head walls in Hume pipe culverts including its painting S/SRI/U | | | | | |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | | | | S/SRI/U | |
| c) | Condition of railings/slab/approach for Bridges | | | S/SRI/U | | |
| 3. | Road Furniture | | | | | |
| a) | Whether sign stones/Pavemen | boards/informatory nt road markings are | /eautionary Board/km & provided and maintained | 200m | Yes/No | |
| 4. | Compliance H | istory | A Comment of the Comm | | | |
| a) | Status of ATR's | s & any others | | | | |

Overall Rating

| Satisfactory (S) | 1 |
|--|---|
| Satisfactory but requires Improvement (\$RI) | - |
| Unsatisfactory (U) | |

work not started.

Arivard 3/12/2020

(Signature)
J.E. Nowada

NAME: