## FIELD INSPECTION REPORT

Date of Inspection: 2	1.12.2020	District: NAWADA		
Division: NAWADA		Length (km): 2.90	10	_
	THE RESERVE OF THE PROPERTY OF THE PARTY OF	ULTAN PUR	A COLUMN TO THE PARTY OF THE PA	
	MAINTENANCE	and and any other from the second	ar in real rivers of the control real real real processing over	- 1
Package No.:		Road Id No.:		
Status of the Project:	Ongoing/Complete	d/Under Maintenance		. ]
Work is a case of:	New Connectivity/	Up gradation/ Maintenance	destroyant plant grown more accept	-
Sl. No.	Parameters to	be checked -		Remarks

Sl. No.	Parameters to be checked -	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing -	_S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3,	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	NA
Satisfactory but requires Improvement (\$RI)	NA
Unsatisfactory (U)	NV

- WORK NOT STARTED \_\_

WITHTO

JE (R.K. Soveranz)

RWD.

(Signature)

NAME: