FIELD INSPECTION REPORT

	f Inspection: 8-		Bhagalberr	
Divisio	Runa	gaon Length (km):		
	of the Road:	MAINTENANCE Chang	Tola chou	UK
		MAINTENANCE Road Id No.:	Of the form of the second second or opposite or the second of the second	
	ge No.: of the Project:	2ngoing/Completed/Under Mainter	minec complete	Hed
	is a case of:	New Connectivity/Up gradation/ M	nintenance	and the second second
Sl. No.		Parameters to be checked		Remarks
1.	Pavement			
a)	Road Junction condition		S/U	
b)	Condition of Surfacing		S/U	
	Riding Quality		S/U	
d)	Road Camber		S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No-
f)	Contraction Joints provided or not (CC Pavement)		Yes/No	
g) ·	Compaction of flank/slope & raincuts if any		Yes/No	
2	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U	
c)	Condition of railings/slab/approach for Bridges		S/SRI/U	
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			
a)	Status of ATR's & any others		No	

Overall Rating

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

37270

(Signature)

NAME: