work not Started yet

FIELD INSPECTION REPORT

77				Tour train		<u> </u>	
						Konta	af
Division: Porticyamsan) Length (km): 314 km							
Name of the Road: Sasaram (Prikramenn) Road - Bensajar Villege							
Scheme/Programme: MAINTENANCE							
Package		Road Id No.: NE.			:H22	000664	
	the Project:		Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance				
100 - 100 -	a case of:	the same was a said	to the state of the second	mark property day	Internative	S. 1.2.9	
SI. No.		ri Pi	irameters	to be checked		- Jane	Remarks
1.	Pavement						
a)	Road Junction condition						S/U
b)	Condition of Surfacing						S/U
	Riding Quality						S/U
d)	Road Camber						S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.						Yes/No
f)	Contraction Joints provided or not (CC Pavement)						Yes/No
	Compaction of flank/slope & raincuts if any						Yes/No
2.	Grass Drainage						
	Condition of head walls in Hume pipe culverts including its painting						S/SRI/U
a)	Condition of Abutment & Wing walls, Slab in RCC culverts						S/SRI/U
b)	Condition of railings/slab/approach for Bridges						S/SRI/U
c)	Road Furniture						
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained						Yes/No
4.	Compliance	History	SE STATE	S	tart		
a)	Status of ATR's & any others Not Start						
Overall	Rating :	Sati	isfactory (S) put requires Impa	rovement	(SRI)	
		Sati	otiofactor	v (U)			
	Unsatisfactory (U)						
~							1 som
							03/14/20
							Signature)
						(1,1)	· D************************************
the state and an	AMMHAN!	DAA	PANDET	To a second			
NAME:	RAMCHAN	-				ė	

Scanned by CamScanner