work not Started yet

FIELD INSPECTION REPORT

Date of Inspection: 62/12/2020 District: Rohr				TAS	
Division: Length (km): 6.				2 3	
Name of the Road: MISSING LINK OF SEMRA - MADRO				HUPUR	ROAD
Scheme/Programme: MAINTENANCE					
Package No.:				22000	693
			eted/Under Maintenance		
Annual and the second of the s			ty/Up gradation/ Maintenanc	e	e Michelle Sin
Sl. No.		Parameter	s to be checked	The Maria	Remarks
1.	Pavement				
a)	Road Junction condition				s/U
b)	Condition of Surfacing				S/U
c)	Riding Quality				S/U
d)	Road Camber				S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				Yes/No
f)	Contraction Joints provided or not (CC Pavement)				Yes/No
g)	Compaction of flank/slope & raincuts if any				Yes/No
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting				s/sri/u
b)	Condition of Abutment & Wing walls, Slab in RCC culverts				S/SRI/U
c)	Condition of railings/slab/approach for Bridges				S/SRI/U
3.	Road Furniture				1 7 4
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				Yes/No
4-20	Compliance I	History			
a)	Status of ATR	's & any others	Not Started		
	grant filter				
Overall l	Rating :	Satisfactory (S)		
Satisfactory but requires Improvement (SRI)					
		Unsatisfactor			
				1	

RAMCHANDER PANDET

(Signature)