

FIELD INSPECTION REPORT

Date of Inspection :	02/12/2020	District:	Nalanda
Division :	HILSA	Length (km):	2.764 km
Name of the Road:	Purbigha OP to Mundipur via Benapur		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl No.	Parameters to be checked	
1.	Pavement	SU
a)	Road Junction condition	SU
b)	Condition of Surfacing	MSS and SDBL works prpns
c)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRU
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRU
c)	Condition of railings/slab/approach for Bridges	S/SRU
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRU)	+
Unsatisfactory (U)	-

ANAND KUMAR
NAME:

[Signature]
02/12