## FIELD INSPECTION REPORT

04.12.2020	District :	MUNGER.	
fur- Tasabur	Length (Km):	1.320 KM	
fur- Tasabur fwo Road Ba Road Manfur.	niyaopur- Kho	asagfus-	Bhadoano-
MAINTENANCE M	2-3054 (NE	: w)	
	Road Id No.:	SL. No 23	
Ongoing/Completed/Unde	Maintenance		
New Connectivity/Up grad	ation/Maintenance		
Parameters to be chec		Remarks	
on condition		S/U	
) Road Junction condition ) Condition of Surfacing		S/U	5
Riding Quality		S/U	5
Camber		S/U	<del>Q</del>
d) Road Camber  Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No	209R
oints provided or not (CC Pavement)		Yes/No	Q.
of flank/slope & raincuts if any		Yes/No	
nage			
dition of head walls in Hume pipe culverts including its		S/SRI/U	× .
f Abutment & Wing walls, S	b in RCC culverts	S/SRI/U	
f railings/slab/approach for B	railings/slab/approach for Bridges		
iture			
ign boards/informatory/cautionary board/Km & es/Pavement road markings are provided and		Yes/No Logo Brand	MC
e History			
R's & any others		No	
	e History TR's & any others		e History

Overall Rating:

Satisfacory (S)	7	
Satisfacory but requires Improvement (SRI)	N·A	,
Unsatisfactory (U)		

NAME: SUKESH KUMAR.
DESIGNATION: A.E

(Signature)