FIELD IN

	는 사람들은 보기 이용하다. <u>-</u>	FIELD INSDE	
Date of	Inspection: 02	FIELD INSPECTION REPORT	
Division	3.311. 02	Cichangani	
Name o	1/18 Mach	110/4/	110100
Scheme		Mathaga Villada Villada	upciolary of the
Package	P No :		
Status	C 140.;	Poad Id No.: 2120580401	
Work is		Ongoing/Completed /Under Maintenance	
\$1. No	a case of:	New Connectivity/ Up gradation / Maintenance	
1.	Parameters to be checked		Remarks
Y	ravement		\s\/U
a)	Road Junction Co	VS/U	
<u>b)</u>	Condition of Sur	V5/U	
<u>c)</u>	Riding Quality	US/U	
d)	Road Camber	V5/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Join	action Joints Provided or not ( CC Pavement)	
g)		tion of fland / shop & raincuts if any	
2.	Cross Drainage		
a)	Condition of hea	n of head walls in Hume pipe culverts including its Painting	
b)	Condition of Abutment & Wing walls, slab in RCC culverts		S/SRI/U
c)	Condition of railings/Slab/approach for Bridges		VS/SRI/U
3.	Road Furniture		
. a)	Whether sign boards/informatory/cautionary Board/km & 200m		Yes/No
	stones/Pavemen		
4.	Compliance Hist	ory	
a)	Status of ATR's 8	& any others	Not pendi

## Overall Rating:

Satisfactory(S)	S
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory(U)	-

Executive Engineer
R.W.D (MAY) 2: R.W.D (W) Division

Kishanganj-Ative Engineer R.W.D. Works Division Kishanganj-1

Superintendent Engineer Work Circle Kishanganj