## FIELD INSPECTION REPORT

		THEOD HASP	ECTION REPORT	
	f Inspection :	1/12/20	District: ARARIA	
			Length (km): 4.195 K·m	
Name (	of the Road: Ku	Pauli Porchi	on to matigari path	
Scheme/Programme:		Pauli Poschin to matigari path MAINTENANCE		
Packag	ge No.:	The second secon	Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Mnintenance		
Work is a case of:		New Connectivity/Up gradation/ Maintenance  Parameters to be checked Remark		Remarks
Sl. No.		and the same of th		
1.	Pavement on going			
a)	Road Junction condition			S/U
b)	Condition of Surfacing //			S/U
	Riding Quality //			S/U
c)	Kluing Quarry			S/U
d)	Road Camber  Whether free from defects such as visible cracks, exposed  Yes/No			
e)	agglegates in case of the			Yes/No
f)	Contraction Joints provided of not (CCT avenues)			Yes/No
g)	Compaction of flank/slope & raincuts if any			
2	Cross Drainage		A/B	
	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
a)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
b)	Condition of Abuthlence wing  Condition of railings/slab/approach for Bridges  S/SI			S/SRI/U
c)	and all has been all the second and			
3.	Road Furniture		D 1/1 0 200-	- PURE TO A SERVICE
a) s	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
- 1	Compliance Histo			
	tatus of ATR's &			NO

Overall Rating

Satisfactory (S)	FOT
Satisfactory but requires Improvement (SRI)	3/1
Unsatisfactory (U)	

Signature)

NAME:
Bindeshwari pomond Ram
At/ Ranigano