FIELD INSPECTION REPORT

| | The state of the s | | | | |
|------------------------|--|----------------------------------|--|--|--|
| Date of Inspection: O | 4-12-2020 | District: Malanda | | | |
| Division: Blarsha | rf | Length (km): 3.45 KM, | | | |
| Name of the Road: M | anibaba Akhada | to Langhri Bighavia Kalyanpur Rd | | | |
| Scheme/l'rogramme: | MAINTENANCE | New Mainterance Policy 2018 | | | |
| Package No.: | | Road 1d No.: | | | |
| Status of the Project: | Ongoing/Completed/Under Maintenance | | | | |
| Work is a case of: | New Connectivity/Up gradation/ Maintenance | | | | |

| No. | Parameters to be checked | Remarks | |
|------|--|---------|-------------|
| 1. | Pavement | | |
| n) | Road Junction condition | |) |
| b) | Condition of Surfacing | | 12 |
| c) | Riding Quality | S/U | 1 S |
| d) | Road Camber S/U | | 1/5 |
| c) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | Yes/No | |
| f) | Contraction Joints provided or not (CC Pavement) | Yes/No | \parallel |
| g) | Compaction of flank/slope & raincuts if any | Yes/No | $\ $ |
| 2 | Cross Drainage | | |
| a) | Condition of head walls in Hume pipe culverts including its painting | s/SRI/U | |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | S/SRI/U | |
| c) | Condition of railings/slah/approach for Bridges | S/SRI/U | |
| 3. | Road Furniture | | 7 |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | | |
| 4.4. | Compliance History | | |
| E) | Status of ATR's & any others | | 7 |
| | | | |

Overall Rating ;

| Satisfactory (S) | |
|---|--|
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | |

(Signature)

NAME: Advind Kuray

DESIGNATION: J-E

Scanned with CamScanner