FIELD INSPECTION REPORT

	1 1043	
	nspection: 04-12-2091 District: Grobalgary	NM
Division		O KM
	the Road: Tala Sipaya to Pakzi	
	Programme: MAINTENANCE	
Package		
	the Project: Ongoing/Completed/Under Maintenance a case of: New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U (S)
b)	Condition of Surfacing	s/ V (U)
c)	Riding Quality	s/y (n)
d)	Road Camber	(2) UNE
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No 110
f)	Contraction Joints provided or not (CC Pavement)	Yes/No Yes
g)	Compaction of flank/slope & raincuts if any	Yes/No No raince
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	s/sri/u (S)
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U HA
3.	Road Furniture	HIS THE
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No JL
4.	Compliance History	
a)	Status of ATR's & any others	NO ATK

Overall Rating

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	(0)

DESIGNATION: Executive Engineer

Scanned by CamScanner

(Signature)