## FIELD INSPECTION REPORT

ate of I	nspection: 05. 12. 20 20 Dis	strict: Muzaffarfom	
Division: MAZ - Fast- 2		Length (km): 3-809 km	
	the Road: Belsend PWD R	oad to Chano chhi	apre
	Programme: MAINTENANCE		
ackage	140.:	oad Id No.:	
Status of	the Project: Ongoing/Completed/Un	der Maintenance	
Work is	a case of: New Connectivity/Up g		
Sl. No.	No. Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
n	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No -
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b).	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/ca stones/Pavement road markings are p	nutionary Board/km & 200m rovided and maintained	In Jorn Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating

Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

(Signature)

NAME: Kamte pet. Single DESIGNATION: JE prinapur