## FIELD INSPECTION REPORT

				and the second s	
-		1 7 2010	Istrict: Nalanda		
vision:	Bilarsho	1	ength (km): 1.80 km.		
	ic Road: NH	-31 Gange Bigha L	Mahahardfur Selachim Bo	di Path	
	ogramme:		w Maintenance Pelicy	2018	
ackage N			oad Id No.:		
	he Project:	Ongoing/Completed/U			
Vork is a case of: New Connectivity/Up gradation/ Maintenance				Daniela	
SI. No.	Parameters to be checked			Remarks	
1.	Pavement				
n)	Road Junction condition			s/U	
b)	Condition of Surfacing			s/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
n	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2	Cross Drain	nge			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4.	Compliance History				
a)	Status of ATR's & any others				

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Autor 20 OY-12-20 (Signature)

NAME: Arvind Kunar

DESIGNATION: J. Q.

hot

NA