## FIELD INSPECTION REPORT

Date of Inspection: 02-12-2020 District: NALANDA					
Division: RWD HARNAUT			Length (km): 7.90 km		
Name of	the Road: L	algant mo	or to Pata	bad.	
	Programme:	MAINTENANCI			
Package No.: Road Id No.:					
	the Project:		ted/Under Maintena		
Work is a case of: New Connectivity/Up gradation/ Maintenance					
Sl. No.	Parameters to be checked				Remarks
1.	Pavement				
a)	Road Junction condition				S/U
b)	Condition of Surfacing 9			S/U	
c)	Riding Quality S				S/U
d)	Road Camber				S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				Yes/No
f)	Contraction Joints provided or not (CC Pavement) N/A Yes/				Yes/No
g)	Compaction of flank/slope & raincuts if any				Yes/No
2,11	Cross Drains	ge	, ja		Z. Lift
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U				
b)	Condition of Abutment & Wing walls, Slab in RCC culverts N/A				S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
<b>建纵</b>	Compliance	History			* .
a)	Status of ATI	R's & any others			NO
Control of the last of the las					

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Casium pronahanana

DESIGNATION:  $\mathcal{F}$