

FIELD INSPECTION REPORT

Date of Inspection :	3-12-20	District:	Nalanda
Division :	Hilera	Length (km):	0.12 km
Name of the Road:	Lost technology road from Toga to Bampur		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance Completed		
Work is a case of:	New Connectivity/Up gradation/ Maintenance upgradation		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition		S
b)	Condition of Surfacing		S
c)	Riding Quality		
d)	Road Camber		S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	CC Not provided
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	-
g)	Compaction of flank/slope & raincuts if any	Yes/No	-
2.	Cross Drainage		
a)	Condition of head walls in Home pipe culverts including its painting	Satisfactory	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	Satisfactory	S
c)	Condition of railings/slab/approach for Bridges	Satisfactory	S
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/10m & 200m stones/Pavement road markings are provided and maintained	Yes/No	yes
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Satisfactory

NAME:

Pradeep Kumar Arya
J.E


3.12.20