MR3054

MR.

FIELD INSPECTION REPORT

Date of Inspection: 02/12/2020 District: Division: Madla Length (km): Name of the Road: 3.500 Ku 40 Scheme/Programme: MAINTENANCE

Package No.: Road Id No.: Status of the Project:

Ongoing/Completed/Under Maintenance Work is a case of

Work is a case of:		New Connectivity/Up gradation/ Maintenance	
SI. No.	Lat 110 de de la mierra de la con-	Parameters to be checked	Remarks
1.	Pavement		canthan dans
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		- S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		-Yes/No
2.	Cross Drai	nage	
a)	Condition of head walls in Hume pipe culverts including its painting		-S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		The same of the sa
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating

Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

(Signature)

NAME: Chambu Medan 910
DESIGNATION: Arts.