

FIELD INSPECTION REPORT

Date of Inspection:	5/12/20	District:	Nalanda
Division:	Hilsa	Length (km):	0.630 km
Name of the Road:	Mina Bazar P.W.D. road Barham purn to Badalpur shangra		
Scheme/Programme:	MAINTENANCE		
Package No.:	Road Id No.:		
Status of the Project:	Ongoing/Completed/Under Maintenance	under maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NO
f)	Contraction Joints provided or not (CC Pavement)	NO
g)	Compaction of flank/slope & raincuts if any	NO
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S SRI S
b)	Condition of Abutment & Wing walls, Slab in RC culverts	S SRI S
c)	Condition of railings/slab/approach for Bridges	S SRI S
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	NO
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME: Pradip Kumar Arya
J.E

Signature
5/12/20