

FIELD INSPECTION REPORT

Date of Inspection :	02/12/2020	District:	Nalanda
Division :	HILSA	Length (km):	2.10 km
Name of the Road:	Bihar - Ekangar road near panchnamesh bul to		
Scheme/Programme:	MAINTENANCE (5th year) harpur hischalga - isla		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance (5th year)		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S S/V
b)	Condition of Surfacing	S S/V
c)	Riding Quality	S S/V
d)	Road Camber	S S/V
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Y Yes/N6
f)	Contraction Joints provided or not (CC Pavement)	Y Yes/N6
g)	Compaction of flank/slope & raincuts if any	Y Yes/N6
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/N6 a few missing
4.	Compliance History	
a)	Status of ATR's & any others	ND

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

ANTANA KUMAR
NAME:

(Signature)