

FIELD INSPECTION REPORT

Date of Inspection :	02/12/2020	District:	Nalanda
Division :	HILSA	Length (km):	6.35 km
Name of the Road:	NH-110 Ekangardih to Parulpur Baulahavan		
Scheme/Programme:	MAINTENANCE (3rd year)		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance (3rd year)		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	
1.	Pavement	S SIV
a)	Road Junction condition	S SIV
b)	Condition of Surfacing	S SIV
c)	Riding Quality	S SIV
d)	Road Camber	S SIV
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NO Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/IV
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/IV
c)	Condition of railings/slab/approach for Bridges	S/SRI/IV
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained.	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	SRI
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

ANJANE KUMAR
NAME:

Signature
02/12/20