FIELD INSPECTION REPORT

	The second secon	The state of the s	manderialestationici estativi estati estati estati	e para de la companya de la deserva de la companya	Construction of the Constr
Date of Inspection : 6	1/12/2020	District:	Tehan.	2699	
The state of the s		Length (km):	1.00 K	m	
Division: Joh. Name of the Road:	NH83 M	ivalifing f	c Bhad	1298	Bayerno
Scheme/Programme:	MAINTENANCE				
Package No.:		Road Id No.:			
Status of the Project:	Ongoing/Completed/Under Maintenance				
Work is a case of:	New Connectivity/Up gradation/ Maintenance				

York is	a case of: New Connectivity Op graduates	Remarks	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement	S/U	
a)	Road Junction condition		
b)	Condition of Surfacing		
c)	Riding Quality		
d)	Road Camber		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
Ŋ	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Rumiture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
	Compliance History	1	
a)	Status of ATR's & any others	No	

Overall Rating

Zalawa Pra a dalah	The state of the s
Satisfactory	(S)
Satisfactory	but requires Improvement (SRI)
Unsatisfacto	ριχ (U)
The same of the sa	

NAME: Surviver Romany
DESIGNATION: AE
Mayor dums from