FIELD INSPECTION REPORT

ate of In	enection : A	-17- 2020 District:	Nalalda	-
ivision :	Bikard	1. coult (k	m): 1.10 km.	
ame of	the Road: Ro	Pair of soul form HH. " .	WVINDERPAS ITT UN	philosi
cheme/l	rogramme:	MAINTENANCE 3054 M	R class?	
ackage	No.:	Road Id N	lo.:	
tatus of	the Project:	Ongoing/Completed/Under Mai	ntepance	-
Vork is	a case of:	New Connectivity/Up gradation		
SI. No.	Parameters to be checked			Remarks
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
<u>d)</u>	Road Camber		S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
ŋ	Contraction Joints provided or not (CC Pavernent)			Yes/No
g)	Compaction of flank/slope & raincuts if any			YesNo
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U	
c)	Condition of railings/slah/approach for Bridges		S/SRI/U	
3.	Road Furniture			* "
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
1.4.	Compliance	Compliance History		
a)	Status of AT	R's & any others		
4				

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

(Signature)

NAME:

Arvind Kunor

DESIGNATION: J.E.,

Scanned with CamScanger