FIELD INSPECTION REPORT

| | | FIELD INSPECT | ION REPURI | |
|---|--|--|--|-------------|
| Date of Ir | spection: ol | | District: Malanola | |
| Name of the Road: Rupair of read from Mirdad to Manauki uh Be | | | | 2 a ouan BV |
| iame of | the Road: Ro | hair of soul from | n Mirdad to Mananki ual | Sagura |
| cuemen | Logramme: | MMILLITATION | | |
| Package | | | Road Id No.: | |
| | the Project: | Ongoing/Completed/U | gradation/ Maintenance | |
| | a case of: | | the second secon | Remarks |
| SI. No. | lo. Parameters to be checked Remark | | | |
| 1. | Pavement | | | |
| a) | Road Junction condition | | | S/U |
| b) | Condition of Surfacing | | | S/U |
| c) | Riding Quality | | | S/U |
| d) | Road Camber | | | s/U |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | | | Yes/No |
| f) | Contraction Joints provided or not (CC Pavement) | | | Yes/No |
| g) | Compaction of flank/slope & raincuts if any | | | Yes/No |
| 2. | Cross Drainage | | | |
| a) | Condition of head walls in Hume pipe culverts including its painting | | | S/SRI/U |
| b) | Condition of | Condition of Abutment & Wing walls, Slab in RCC culverts | | |
| c) | Condition of railings/slab/approach for Bridges | | | S/SRI/U |
| 3. | Road Furni | Road Furniture | | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | | | Yes/No |
| 4. | Compliance History | | | |
| a) | Status of AT | R's & any others | | |

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

2000

(Signature)

NAME: Birnod Kumar Shiph

DESIGNATION: $\sqrt{5}$

Scanned with CamScanner

Scanned with CamScanner