FIELD INSPECTION REPORT

		11.010.00	District: Halanda	1.0
Date of Inspection: 04 12/2020			Length (km):	
Division: gikar sharlf Length (km): Name of the Road: Rotair of recoil from Raturi Bazar to NH3 Bhogan Bryh				
Name of	the Road: Lor	MAINTENANCE	m R 3054	
Package No.: I Ongoing/Completed/U				
Work is a case of: New Connectivity/Up gradation/ Maintenance				
SL No.	2 30 1 (c) 1			Remarks
1.	Pavement	-11		
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
Ŋ	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Draina	ige	7	
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furnitu	ire		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			

Overall Rating

a)

Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

> @105ty/ 04/12/2220 (Signature)

NAME:

Binod Kumar Shiph

Status of ATR's & any others

DESIGNATION: J. E

Scanned with CamScanner

Scanned with CamScanner