## FIELD INSPECTION REPORT

Date of 1	inspection: 0	532/2020 Matrict: Nalander.	1. 100	
Division: Biharshazik. Length (km): 4.50 k.M.				
	the Roads Ro	power of soud from Ketoa to hopelbas	village ma	Parnava High
Name of the Road: Repair of sead from Kotoa to Gopalbad village this parnaua Scheme/Programme: MAINTENANCE MR 3054-				
Package		Road Id No.:		
Status of the Project: Ongoing/Completed/Under Maintenance				
Work is a case of: New Connectivity/Up gradation/ Maintenance				
\$1. No.	Parameters to be checked		Remarks	
1.	Pavement			
n)	Road Junction	condition	S/U	
b)	Condition of S	Surfacing	S/U	
c)	Riding Quality		S/U	
d)	Road Camber		S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			
f)	Contraction Joints provided or not (CC Pavement)		Yes/No	
g)	Compaction of flank/slope & raincuts if any		Yes/No	
2.	Cross Drainage			1
a)	Condition of	nead walls in Hume pipe culverts including its painting	s/sri/u	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U	NB
c)	Condition of railings/slab/approach for Bridges		S/SRI/U	] h -
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4.	Compliance	History		
8)	Status of ATI	R's & any others		
THE RESERVOIR SHAPE OF THE PARTY OF THE PART				

**Overall Rating** 

Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

\* Desplicate entry.

alreday entered in old MR3054

(Signature)

NAME: MY Meis Abmad

**DESIGNATION:** 

Scanned with CamScanner

Scanned with CamScanner