## FIELD INSPECTION REPORT

Date of l	nspection: 02-12-2020	District: NALANDA	
Division:		Length (km): 7.10KM	
Name of	the Rand: Repair of Road for	som sekkbura of NH300 to	charelo gahzarai R
	Programme: MAINTENANCE	Via Talalbur Be	adrowali
Package		Road Id No.:	
-		ed/Under Maintenance	
		/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked Ro		Remarks
1.	Pavement .		
a)	Road Junction condition		S/U
b)	Condition of Surfacing S		S/U
c)	Riding Quality S		S/U
d)	Road Camber S		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2,4	Gross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts NA		S/SRI/U
c)	Condition of railings/slab/approa	ch for Bridges N/A	S/SRI/U
<b>3.</b> ;	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		I CS/140
	Compliance History		
a)	Status of ATR's & any others		NO

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Casim Ko makarona

DESIGNATION: J.E

Scanned with CamScanner