FIELD INSPECTION REPORT

Date of I	aspection: 02-12-2020 District: NACANDA		
Division: PhiD Hoonaut - Length (km): 3.20 Km)			
Name of	the Road: Repair of Road from Okaran makfor	RWD Road to Hos	sanchak
Scheme/I	Programme: MAINTENANCE	ore to Gram	Keusa.
rackage 140.:			
	the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance			
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality S	S/U	
d)	Road Camber S	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2	Cross Drainage	- Total	
a)	Condition of head walls in Hume pipe culverts including its painting	RIS/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
	Compliance History		
a)	Status of ATR's & any others	NO	

NAME: Casium for malorana

Satisfactory (S)

Unsatisfactory (U)

Satisfactory but requires Improvement (SRI)

DESIGNATION: JE

Overall Rating

Scanned with CamScanner

SRI