

FIELD INSPECTION REPORT

Date of Inspection :	3-12-20	District:	Nalanda
Division :	HISA	Length (km):	11.45 km
Name of the Road:	Telhara to Moona Bazar		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

under maintenance
upgradation & gradation

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S U S
b)	Condition of Surfacing	S U S
c)	Riding Quality	S U
d)	Road Camber	S U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No Yes
g)	Compaction of flank/slope & rainouts if any	Yes/No NO
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/RI/U SRT
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/RI/U SRT
c)	Condition of railings/slab/approach for Bridges	S/RI/U SRT
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No Yes
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRT
Unsatisfactory (U)	

NAME:

Pradeep Karmar Arya
J.E

[Signature]
31/12/20