## FIELD INSPECTION REPORT

Date of I	nspection: 0	3/12/20	District:	WAIT		
Division: mohanda Length (km): 14,8 15 m.						
Name of the Road: Repair of Road Kon Lhayung to Kongon						
Scheme/Programme:  MAINTENANCE  Road Id No.:						
Package ivo.						
Status of the Project: Ongoing/Comple			/Up gradation/ Maintenance			
The Person of th		Parameters to be checked			Remarks	
Sl. No.	Payement					
1.	Road Junction condition				√\$/U	
a)					S/U·	
b)	Condition of Surfacing					V\$/U
c)	Riding Quality					√S/U
d)	Road Camber  Whether free from defects such as visible cracks, exposed					
e)	aggregates in case of CC Pavement.					Yes/No
(1)	Contraction Joints provided or not (CC Pavement)					Yes/No
g)	Compaction of flank/slope & raincuts if any					√Yes/No
<b>2.</b>	Cross Drainage					
a)	Condition of head walls in Hume pipe culverts including its painting					S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts					S/SRI/U
c)	Condition of railings/slab/approach for Bridges					S/SRI/U
3.	Road Furniture					
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained					✓Yes/No
4.	Compliance History					
a)	Status of ATR's & any others				NO	
Overall Rating : [State for down (S)]						
Overall	kating :	Satisfactory (S)				
		Satisfactory bu	Satisfactory but requires Improvement (\$RI)			'SRI'
		Unsatisfactory	(U)			

NAME: SATYRNDRA PRASADZAL

(Signature) 03/12/20