## FIELD INSPECTION REPORT

Date of In	aspection: 4	112/2	District: Nalanda	
ivision	and the second s	<u> </u>	Length (km): 12.010 Km	
ame of		ao Bhui Ma	cizara to kulhuha Road	
cheme/l	rogramme:	MAINTENAN	CE	
Package No.:			Pleted Inder Maintenance out of F	ive year n
		Ongoing Com	vity/Up gradation/ Maintenance	
	Water a State of		William Control of the Control of th	Remarks
Sl. No.	Parameters to be checked R			
1.	Pavement	Pavement		
8)	Road Junction condition			S/U
bì	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			ST
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
0	Contraction Joints provided or not (CC Pavement)			Yeshi
gj	Compaction of flank/slope & raincuts if any			Yes No
2.	Cross Drainage			
2)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SREET
6)	Condition of railings/slab/approach for Bridges			S/SRITI
3.	Road Furniture			
a)	D. sulless & 200m			Yes/No
4.	Compliance History			
a)	Status of ATR's & any others			
	1			
Overall	Rating :	Satisfacto	ry (S)	
		Satisfacto	ry but requires Improvement (SRI)	
			(III)	

Unsatisfactory (U)

Ramprewesh kymor SE Ben (Signature)