

FIELD INSPECTION REPORT

Date of Inspection : 04-12-2020

District: Nalanda

Location : H/Sa

Length (km):

4.80 Km

Name of the Road: Kochra to Sidapur via Champur Road

Name/Programme: MAINTENANCE

Page No.:

Road Id No.:

Status of the Project: Ongoing/Completed/Under Maintenance

Work is a case of: New Connectivity/Up gradation/ Maintenance

No.	Parameters to be checked	Remarks
	Pavement	
	Road Junction condition	S/U
	Condition of Surfacing	S/U
	Riding Quality	S/U
	Road Camber	S/U
	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
	Contraction Joints provided or not (CC Pavement)	Yes/No
	Compaction of flank/slope & raincuts if any	Yes/No
	Cross Drainage	
	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
	Condition of railings/slab/approach for Bridges	S/SRI/U
	Road Furniture	
	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
	Compliance History	
	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

✓ S

4/12/20

(Signature)